

PURE Help Centre

[Knowledgebase](#) > [All Other Radios](#) > [iDock Products](#) > [Radio headphone output is disabled when docking my iPod\ iPhone \(Contour 100Di\)](#)

Radio headphone output is disabled when docking my iPod\ iPhone (Contour 100Di)

Pure Support - UK - 2025-10-20 - [iDock Products](#)

Radio headphone output is disabled when docking my iPod\ iPhone (Contour 100Di)

Please note that the headphone output remains disabled while any Apple device is docked in the Contour 100Di. Removing the Apple device will re-enable the headphone output on this radio.